

WASHINGTON STATE DEPARTMENT OF ECOLOGY—TOXICS CLEANUP PROGRAM

March 29, 2018

CONTENTS

Formal Cleanups	1		
Independent Cleanup News & Notes Glossary Site Information Online	11 16 17 19		
		Regional Office Addresses	19

Sign up to receive the Site Register via email: http://listserv.ecology.wa.gov/scripts/wa-ECOLOGY.exe?A0=SITEREGISTER

Find past issues: tinyurl.com/EcologySiteReg

For information about public comment periods, meetings and hearings, visit Ecology's Public Involvement Calendar at https://ecology.wa.gov/events-listing.

Questions? Please contact Cheryl Ann Bishop at 360-407-6848 or cherylann.bishop@ecy.wa.gov.

Site contacts are found after each entry.

To request Americans with Disabilities Act accommodation including materials in a format for the visually impaired, please call 360-407-7170 or visit ecology.wa.gov/ Accessibility. Persons with impaired hearing may call Washington Relay Service at 711. Persons with a speech disability may call 877-833-6341.

FORMAL CLEANUPS

Ecology oversees complex cleanup sites to ensure that your health and that of the environment are protected.

KING COUNTY

Schlueter Property Facility Site 2886743 Cleanup 1348 1515 196th Street SE, ID# Site ID#

Bothell

Public Comment Period: 3/2/2018 - 4/2/2018

Proposed removal from the Hazardous Sites List available for review and public comment

After Ecology received complaints of illegal dumping on the property, the Snohomish Health District collected soil samples at the site in February 2005. A Site Hazard Assessment was then completed on Ecology's behalf. The SHA identified petroleum products and heavy metals as potential contaminants released as a result of the illegal dumping. The property was added to the Ecology Confirmed and Suspected Contaminated Sites List in February 2006. The resulting SHA rank for the site was 4, based on a scale of 1 to 5, where 1 represents the greatest potential impact to human health and the environment.

Ecology has determined the site cleanup meets state cleanup standards and is protective of human health and the environment. Therefore, Ecology is proposing to remove the site from the Hazardous Sites List.

Ecology invites you to review and comment on the:

- No Further Action Letter
- Initial Characterization Subsurface Investigation
- Additional Soil Sampling Report

Send your written comments to (please reference Schlueter): Michael Warfel, site manager michael.warfel@ecy.wa.gov or 3160 160th Ave SE, Bellevue, WA, 98008

Documents can be viewed at:

- Mill Creek Public Library, 15429 Bothell Everett Hwy, Mill Creek, 425-337-4822
- Ecology's Bellevue office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email nwro_public_request@ecy.wa.gov for an appointment)
- Schlueter Property Cleanup webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=1348

Maury Island Open Space Cleanup Site

Facility Site ID# 2901216

Cleanup Site ID#

1532

Maury Island

Public Comment Period: 4/9/2018 - 5/23/2018

Public Meeting: 4/11/2018

Documents available for public comment and review

Ecology invites you to review a cleanup plan, and associated documents, for the Maury Island Open Space Cleanup Site on Maury Island. The plan is part of a legal agreement between Ecology and King County that requires them to design the cleanup work described in the plan. A future legal agreement will require them to implement the work. The following documents are available for review:

- Cleanup Action Plan: describes the cleanup work to address site contamination.
- Remedial Investigation: details an investigation of the nature and extent of contamination at the site.
- Feasibility Study: identifies 5 alternatives, and a preferred alternative, for addressing the contamination.
- State Environmental Policy Act (SEPA)-Determination of Non-Significance (DNS): Ecology determination that the cleanup work is not likely to harm the environment.

Ecology will hold a public meeting to provide more information:

Wednesday, April 11, 2018 7 p.m. – 9 p.m. Vashon High School Theater 9600 SW 240th Street Vashon, WA 98070

Submit comments to:

Cris Matthews, project manager

360-255-4379

cris.matthews@ecy.wa.gov or online bit.ly/Ecology-MauryIsland-Comments

Documents can be viewed at:

- Vashon Public Library, 17210 Vashon Highway SW, Vashon Island, 206-463-2069
- Northwest Regional Office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email NWRO Public Request@ecy.wa.gov for an appointment)
- Ecology's Maury Island Open Space web page: bit.ly/Ecology-MauryIsland

CHS Auburn Site (Cenex Valley Supply Coop) Facility Site ID# 2487 Cleanup Site ID# 5119 238 8th Street SE, Auburn

Public Comment Period: 4/6/2018 - 5/7/2018

CHS Auburn Draft Consent Decree and cleanup documents available for public review and comment

Ecology and CHS Inc., will enter into a legal agreement called a consent decree that requires cleanup at the CHS Auburn site (also known as Cenex Valley Supply Coop). The consent decree, along with the Remedial Investigation (RI) and Feasibility Study (FS) reports and a Draft Cleanup Action Plan (DCAP) are available for public review and comment.

The site covers approximately 10.5 acres. The identified chemicals of concern are petroleum hydrocarbon compounds (diesel, gasoline, oil, benzene, toluene, ethylbenzene, and xylenes) in soil and groundwater. Remedial activities have been ongoing since 1994, with one groundwater remediation system, designated as the Central System, currently active. The contaminated groundwater plume has reduced in size since 1994. The proposed cleanup will address the remaining soil and groundwater contamination in a targeted area of the site using focused air sparging, monitored natural attenuation, and institutional controls.

You are invited to comment on the following documents:

- RI report, which describes the nature and extent of contamination and remediation at the site
- FS, which describes alternatives evaluated to clean up the site and the preferred alternative
- DCAP, which describes the proposed remedial alternative to clean up the site
- Draft Consent Decree, the legal agreement filed in court that requires CHS Inc. to conduct the cleanup
- State Environmental Policy Act (SEPA) Checklist and Determination of Non-Significance (DNS)
- Updated Public Participation Plan. The plan outlines and describes the tools and approaches that Ecology will use to inform the public about site activities, and it identifies opportunities for the community to become involved in this process.

Send your written comments to (indicate CHS Auburn Cleanup in your comment):

Jerome Cruz

jerome.cruz@ecy.wa.gov or mail to 3190 160th Ave SE, Bellevue, WA 98008

Documents can be viewed at:

- Auburn Regional Library, 1102 Auburn Way S, Auburn, 253-931-3818
- Northwest Regional Office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email NWRO Public Request@ecv.wa.gov for an appointment)
- Ecology's CHS Auburn webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=5119

Bothell Former Hertz site

Facility Site ID# 11687976 Cleanup Site ID# 7906

18030 Bothell Way NE, Bothell

Public Comment Period: 4/12/2018 - 5/11/2018

Bothell Former Hertz Agreed Order and environmental documents available for public review and comment Ecology and the City of Bothell will enter into an agreement called an Agreed Order that requires the city to clean up the Bothell Former Hertz site.

The site is generally located on both sides of the newly constructed SR 522 roadway, between Bothell Way NE and 98th Avenue NE / NE 180th Street, in Bothell, Washington. A Hertz Rentals facility with an office, warehouse and shop building, smaller buildings, and asphalt-paved parking and storage formerly occupied the site.

During removal of USTs in 1993, petroleum contaminated soils were found to extend underneath the former buildings. Chlorinated solvents (chemicals commonly associated with dry cleaners) were found in groundwater. These came from the Bothell Service Center Simon & Son Cleanup site, which is being cleaned up separately. Interim action soil cleanups were conducted in 2010, 2012, and 2013.

Chemicals of concern remaining in groundwater after the interim action cleanups are:

Total petroleum hydrocarbons (gasoline, diesel and motor oil range)

- Arsenic
- Halogenated volatile organic compounds (HVOCs), from the adjacent Bothell Service Center Simon & Son dry cleaning site, which is a separate state cleanup site.

You are invited to comment on the following documents:

- Draft Agreed Order to clean up the site.
- Draft Remedial Investigation/Feasibility Study (RI/FS)
- Draft Cleanup Action Plan (DCAP)
- Draft Compliance Monitoring Plan
- Updated Public Participation Plan
- State Environmental Policy Act (SEPA) Checklist and draft Determination of Non-significance (DNS)

The 2011 Agreed Order (No. DE 8375) to conduct the RI/FS and write the DCAP has been closed out. The new Agreed Order for cleanup will be finalized after Ecology has reviewed all the public comments on the above documents and determined that no significant changes are necessary.

Send your written comments to (indicate Bothell Former Hertz site in your comment):

Jerome Cruz

jerome.cruz@ecy.wa.gov or mail to 3190 160th Ave SE, Bellevue, WA 98008

Documents can be viewed at:

- City of Bothell City Hall, 18415 101st Ave NE, Bothell, 425-806-6100
- Bothell Public Library, 18215 98th Ave NE, Bothell, 425-486-7811
- Northwest Regional Office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email NWRO_Public_Request@ecy.wa.gov for an appointment)
- Ecology's Bothell Former Hertz webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=7906

Bothell Landing

Facility Site ID# 73975762 Cleanup Site ID# 3013

18120, 18126, 18132 Bothell Way NE & 10001 Woodinville Dr, Bothell

Public Comment Period: 4/12/2018 - 5/11/2018

Bothell Landing Agreed Order and environmental documents available for public review and comment Ecology and the City of Bothell will enter into an agreement called an Agreed Order to clean up the Bothell Landing site. The site is generally located at the intersection of Woodinville Drive/SR 522 and Bothell Way

NE/ former SR 527, in Bothell, Washington. The city acquired properties on which the site lies in 2008 for

construction of the SR 522 realignment.

A strip mall, restaurants, and historic gas stations with multiple abandoned petroleum underground storage tanks (USTs) formerly occupied the site. Petroleum hydrocarbons associated with the service stations were found in soil and groundwater. Five USTs were removed during construction of the park in 1998. Chlorinated solvents (chemicals commonly associated with dry cleaners) were found in groundwater. These came from the Ultra Custom Care Cleaners site, which is being cleaned up separately. Interim action soil cleanups of petroleum hydrocarbons were conducted in 2010, 2013, 2014, 2015, and 2017.

Chemicals of concern remaining after the interim action soil cleanups are:

- In soil: Gasoline range petroleum hydrocarbons and benzene
- In groundwater: Arsenic

You are invited to comment on the following documents:

- Draft Agreed Order to clean up the site
- Draft Remedial Investigation/Feasibility Study (RI/FS) Report
- Draft Cleanup Action Plan (DCAP)
- Draft Compliance Monitoring Plan
- Updated Public Participation Plan
- State Environmental Policy Act (SEPA) Checklist and draft Determination of Nonsignificance (DNS).
- The 2009 Agreed Order (No. DE 6294) to conduct the RI/FS and write the DCAP has been closed out. The new Agreed Order for cleanup will be finalized after Ecology has reviewed all the public comments on the above documents and determined that no significant changes are necessary.

Send your written comments to (indicate Bothell Landing in your comment):

Jerome Cruz

jerome.cruz@ecy.wa.gov or mail to 3190 160th Ave SE, Bellevue, WA 98008

Documents can be viewed at:

- City of Bothell City Hall, 18415 101st Ave NE, Bothell, 425-806-6100
- Bothell Public Library, 18215 98th Ave NE, Bothell, 425-486-7811
- Northwest Regional Office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email NWRO Public Request@ecy.wa.gov for an appointment)
- Ecology's Bothell Landing webpage: https://fortress.wa.gov/ecv/gsp/Sitepage.aspx?csid=3013

Bothell Paint & Decorating

Facility Site ID# 93536765 Cleanup Site ID# 3051

18004 & 18005 Bothell Way NE, Bothell

Public Comment Period: 4/12/2018 - 5/11/2018

Bothell Paint Agreed Order and environmental documents available for public review and comment Ecology and the City of Bothell will enter into a new agreement called an Agreed Order to clean up the Bothell Paint and Decorating site. The site is generally located along Bothell Way NE / SR 522 west of 98th Avenue NE in Bothell, Washington.

Historical operations on the property included automobile repair and dealerships, retail paint and flooring, and sandblasting. There was one underground storage tank (UST) containing gasoline, which was removed in 1988. Petroleum hydrocarbons including gasoline were found in soil and groundwater. Interim action soil cleanups for petroleum hydrocarbons and metals were conducted in 2010, 2013, and 2014.

Chemicals of concern remaining at the site after the interim action cleanups are:

- In soil: Gasoline and motor oil-range petroleum hydrocarbons
- In groundwater: Diesel and motor oil range petroleum hydrocarbons, and arsenic

Ecology invites comments on the following documents:

- Draft Agreed Order to clean up the site.
- Draft Remedial Investigation/Feasibility Study (RI/FS) report
- Draft Cleanup Action Plan (DCAP)
- Draft Compliance Monitoring Plan
- Updated Public Participation Plan
- State Environmental Policy Act (SEPA) Checklist and draft Determination of Non-significance (DNS)
- The 2009 Agreed Order (No. DE 6296) to conduct the RI/FS and write the DCAP has been closed out. The new Agreed Order for cleanup will be finalized after Ecology has reviewed all the public comments and determined that no significant changes are necessary.

Send your written comments to (indicate Bothell Paint & Decorating in your comment): Jerome Cruz

jerome.cruz@ecy.wa.gov or mail to 3190 160th Ave SE, Bellevue, WA 98008

Documents can be viewed at:

- City of Bothell City Hall, 18415 101st Ave NE, Bothell, 425-806-6100
- Bothell Public Library, 18215 98th Ave NE, Bothell, 425-486-7811
- Northwest Regional Office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email NWRO_Public_Request@ecy.wa.gov for an appointment)
- Ecology's Bothell Paint & Decorating webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=3051

Port of Seattle Terminal 91 2001 W Garfield St Seattle

Facility Site ID# 24768

Cleanup Site ID#

2674

T-91 Submerged Lands Area Preliminary Investigation – Surface Sediment Characterization Results Received

The Terminal 91 Complex (T91 Complex) is located in an industrial area in the Interbay neighborhood of Seattle. Various railroads, land development companies, and private individuals owned the property from the late 1800s through 1920. The Great Northern Railroad began to develop the area in the early 1900s by filling in the area between Magnolia Bluff and Queen Anne Hill. Filling continued through the 1940's.

The T91 Complex was operated by several oil companies from 1926 until 1941, when the U.S. Navy took possession. The Port purchased the facility in the 1970s. A four-acre parcel of the T91 Complex is the site of a former tank farm. Constructed in the 1920s, it operated as a fuel storage facility until it was demolished in 2005. In 1992, the owner of the tank farm, Burlington Environmental Inc., was issued a permit to operate as a dangerous waste treatment and storage facility. Although the permit is no longer active, the Port is responsible for cleanup of contamination at the site.

Contamination at the site include petroleum products, volatile organic compounds, semi-volatile organic compounds, metals, polychlorinated biphenyls, and discarded military munitions, and affects the soil, groundwater, and marine sediments.

Tom Mackie, site manager 509-575-2803 or thomas.mackie@ecy.wa.gov

Documents can be reviewed at:

- Ecology's Bellevue office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email nwro public request@ecy.wa.gov for an appointment)
- Central Regional Office, 1250 W Alder St, Union Gap (call **509-454-7658** or email **cropublicrequest@ecy.wa.gov** for an appointment)
- Ecology's Port of Seattle Terminal 91 webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=2674

Univar USA INC - Kent

Facility Site ID# 13862483 Cleanup Site ID# 969

8201 S 212th St, Kent

2017 Annual Groundwater Monitoring Report received

Univar USA, Inc. is a nationwide company that stores, packages, and distributes a variety of chemical products. The Univar facility in Kent has a warehouse, office, dock, and parking areas on an eleven-acre site, surrounded by other commercial and industrial properties. Beginning in the 1990s, Ecology investigated contamination from waste management activities and accidental chemical releases. Studies showed that soil in two areas of the eastern portion of the site are contaminated with organic chemicals and chlorinated compounds.

Groundwater is also contaminated. Most of the groundwater contamination remains located beneath the property. Some contaminants in the deeper part of the aquifer have flowed north under 212th Street and beneath an adjacent industrial property.

Univar has been implementing the Cleanup Action Plan, which includes:

- Treatment of contaminated areas using enhanced reductive dechlorination
- Monitored natural attenuation for treatment of the down-gradient groundwater plume
- Institutional controls to assure long-term protection of human health and the environment
- An environmental covenant placed on the property. This covenant is required because contaminants in excess of cleanup standards will remain on the property after the cleanup action.

Treatment of the source areas and ongoing groundwater sampling. The sampling shows how much groundwater contamination is still present. The sampling information is also used to assess the effectiveness of treatment, so it can be adjusted as necessary.

Tom Mackie, site manager 509-575-2803 or thomas.mackie@ecy.wa.gov

Documents can be reviewed at:

- Ecology's Bellevue office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email nwro_public_request@ecy.wa.gov for an appointment)
- Central Regional Office, 1250 W Alder St, Union Gap (call **509-454-7658** or email **cropublicrequest@ecy.wa.gov** for an appointment)
- Ecology's Port of Seattle Terminal 91 webpage: https://fortress.wa.gov/ecv/gsp/Sitepage.aspx?csid=969

WHATCOM COUNTY

Georgia Pacific West Cleanup site

Facility Site ID# 14

Cleanup Site ID# 2279

Bellingham

Public Comment Period: 3/12/2018 – 4/10/2018

Environmental report available for review and public comment

Ecology invites you to comment on a feasibility study (environmental report) that evaluates cleanup alternatives for contamination within the Chlor-Alkali area of the Georgia Pacific West site in Bellingham.

The Port of Bellingham prepared the report with Ecology oversight. The Port identified and evaluated a range of cleanup alternatives, leading to a preferred alternative. All of this work is detailed in the report. Ecology will also hold a public meeting to provide more information and collect comments:

Public Meeting

March 15, 6-8 p.m.

Ecology Bellingham Office (new location next to Squalicum Creek Park)

913 Squalicum Way, Unit 101, Bellingham

Brian Sato, project manager

425-649-7265 or Brian.Sato@ecy.wa.gov

Documents can be reviewed at:

- Bellingham Public Library, 210 Central Avenue, Bellingham, WA 98225, 360-778-7323
- Ecology's Bellingham office (call Linsay Albin at 360-255-4400 for an appointment).
- Ecology's Bellevue office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email nwro public request@ecy.wa.gov for an appointment)
- Ecology's Georgia Pacific West Cleanup site: http://bit.ly/Ecology-GPWest

YAKIMA COUNTY

Medic 1 Facility

Facility Site ID# 16374394 Cleanup Site ID# 5597

111 S 3rd Avenue, Yakima

Public Comment Period: 3/15/2018 - 4/14/2018

Proposed removal from the Hazardous Sites List available for review and public comment

Ecology is providing an opportunity for the public to comment on the proposed removal of the Medic 1 Facility from the Hazardous Sites List. The contaminant is the result of a leaking underground storage tank and it affected the soil and groundwater.

Jeff Newschwander

509-454-7842 or Jeff.Newschwander@ecy.wa.gov

Supporting documents are available for review at the following locations:

- Yakima Public Library, 102 N 3rd Street, Yakima
- Ecology Central Regional Office, 1250 W Alder Street, Union Gap
- Medic 1 Facility webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=5597

Southgate Laundry

Facility Site ID# 482

Cleanup Site ID#

3399

1020 S 3rd Ave, Yakima

Public Comment Period: 3/12/2018 - 4/10/2018

Proposed removal from the Hazardous Sites List available for review and public comment

Ecology is providing an opportunity for the public to comment on the proposed removal of the Southgate Laundry site from its Hazardous Sites List.

The contaminant is the result of the site operating as a dry cleaner from 1978 to 1997, within the Yakima Railroad area. Tetrachloroethylene, a common solvent with many commercial and industrial uses, was reported in 1978. Further investigation confirmed that soil had been contaminated.

Kyle Parker, site manager 509-454-7833 or Kyle.Parker@ecy.wa.gov

Documents can be reviewed at:

- Central Regional Office, 1250 W Alder St, Union Gap (contact the public records coordinator for an appointment: 509-454-7658 or cropublicrequest@ecy.wa.gov)
- Yakima Public Library, 102 N 3rd St, Yakima
- Ecology's Southgate Laundry webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=3399

Coleman Oil Yakima Bulk Plant

Facility Site ID# 4233

Cleanup Site ID#

13200

1 East I Street, Yakima

Public Comment Period: 2/27/2018 - 3/29/2018

Agreed Order available for public comment and review

Ecology is providing an opportunity for the public to comment on the Agreed Order for the completion of a Remedial Investigation and Feasibility Study for the Coleman Oil Yakima Bulk Plant site.

The contaminant is the result of a spill of diesel fuel in underground piping and a gasoline spill to the subsurface.

Frank Winslow, site manager 509-454-7835 or frank.winslow@ecy.wa.gov

Documents can be reviewed at:

- Central Regional Office, 1250 W Alder St, Union Gap (contact the public records coordinator for an appointment: 509-454-7658 or cropublicrequest@ecv.wa.gov)
- Yakima Public Library, 102 N 3rd St, Yakima
- Ecology's Coleman Oil webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=13200

Washington Central Railroad Roundhouse

Facility Site ID# 545

Cleanup Site ID#

4945

6 E Arlington, Yakima

Public Comment Period: 3/29/2018 - 4/28/2018

Proposed removal from the Hazardous Sites List available for review and public comment

Ecology is providing an opportunity for the public to comment on the proposed removal of the Washington Central Railroad Roundhouse site from the Hazardous Sites List.

The contaminant is the result of the site was used as a railroad engine maintenance and repair facility for over 100 years, starting in the late 1800's. Possible PCE was used to degrease engine parts as part of the engine maintenance.

Kyle Parker, site manager 509-454-7833 or Kyle.Parker@ecy.wa.gov

Documents can be reviewed at:

- Central Regional Office, 1250 W Alder St, Union Gap (contact the public records coordinator for an appointment: 509-454-7658 or cropublicrequest@ecy.wa.gov)
- Yakima Public Library, 102 N 3rd St, Yakima
- Ecology's Washington Central Railroad webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4945

Ultra Yield Micronutrients (Kronos, Bay Zinc)

Facility Site ID# 17964725 Cleanup Site ID#

1444

213 W Moxee Ave, Moxee

Public Comment Period: 3/29/2018 - 4/28/2018

2017 Annual Report for Well Water Sampling Ultra Yield Micronutrients Facility received

This site has been produced zinc micronutrient fertilizer since 1972. Raw materials used in the manufacturing processes were dry, powder or granular, ash-like materials rich in zinc and other metals. These materials were typically reacted with sulfuric acid to extract the zinc. The final product was dried into granules or retained in liquid form, then sold for agricultural use. Since some of the materials used in the manufacturing process were considered to be hazardous waste and since some of that material was released at the site, the site is being managed as a Resource Conservation and Recovery Act (RCRA) Corrective Action. RCRA Corrective Action Sites are cleaned up in accordance with Washington's Model Toxics Control Act.

Tom Mackie, site manager

509-575-2803 or thomas.mackie@ecy.wa.gov

Documents can be reviewed at:

- Central Regional Office, 1250 W Alder St, Union Gap (contact the public records coordinator for an appointment: 509-454-7658 or cropublicrequest@ecy.wa.gov)
- Northwest Regional Office, 3190 160th Ave. SE, Bellevue (call 425-649-7190 or email NWRO Public Request@ecy.wa.gov for an appointment)
- Ecology's Ultra Yield webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=4444

INDEPENDENT CLEANUPS

A property owner may conduct an independent cleanup of contamination and submit reports to Ecology.

Independent Cleanup Contacts

Central Regional Office: Public Records Coordinator at cropublicrequest@ecy.wa.gov or 509-454-7658

Eastern Regional Office: Kathy Falconer at Kathy.Falconer@ecy.wa.gov or 509-329-3568
Northwest Regional Office: Donna Musa at Donna.Musa@ecy.wa.gov or 425-649-7136

Southwest Regional Office: Kim Cross at Kim.Cross@ecy.wa.gov or 509-329-3568

BENTON COUNTY

Curleys Texaco

Facility Site ID# 91996575 Cleanup Site ID# 11988

294 Williams Blvd Richland

Soil Delineation Report Received

Date Report Received: 3/14/2018

Name of Report: Additional Pump Island Petroleum Contaminated Soil Delineation Report

Date of Report: 3/5/2018
Type of Report: investigation
Contaminants Reported: petroleum

Affected Media: soil

Contact: Central Regional Office Public Records Coordinator

509-454-7658 or RecordsOfficer@ecy.wa.gov

Ben Franklin Transit Co

Facility Site ID# 319 Cleanup Site ID# 7012

1000 Columbia Park Trail, Richland

Groundwater Monitoring Report Received

Date Report Received: 3/22/2018

Name of Report: January 2018 Groundwater Monitoring Event

Date of Report: 3/9/2018

Type of Report: groundwater monitoring

Contaminants Reported: petroleum Affected Media: petroleum groundwater

Contact: Central Regional Office Public Records Coordinator

509-454-7658 or RecordsOfficer@ecv.wa.gov

Sun Mart 11 Facility Site ID# 5574663 Cleanup Site ID# 12051

7707 W Deschutes Ave, Kennewick

Groundwater Monitoring Report Received

Date Report Received: 3/20/2018

Name of Report: Groundwater Monitoring Report

Date of Report: 3/16/2018

Type of Report: groundwater monitoring

Contaminants Reported: petroleum Affected Media: groundwater

Contact: Central Regional Office Public Records Coordinator

509-454-7658 or RecordsOfficer@ecy.wa.gov

CLARK COUNTY

Rainier Springs Hospital

Facility Site ID# 12716

Cleanup Site ID# 13315

2711 NE 129th St, Vancouver

Determination of No Further Action

This site is cleaned up. A total of 195.53 tons of petroleum hydrocarbon contaminated soil was removed and disposed of at a permitted landfill. In May 2017, petroleum contaminated fill was identified during geotechnical evaluation prior to construction of a new hospital. The release was reported to Ecology in July 2017. Soils were excavated until contaminant concentrations were less than the MTCA Method A cleanup levels. Confirmatory soil and groundwater sampling analytical results were all less than the applicable MTCA cleanup levels.

Contact: Tim Mullin

360-407-6265 or Tim.Mullin@ecy.wa.gov

GRANT COUNTY

Port of Moses Lake Diesel Spill Site

Facility Site ID# 612

Cleanup Site ID# 14469

7810 Andrews Street Northeast, Moses Lake

Determination of No Further Action

Ecology has determined that no further action is necessary at the Port of Moses Lake Diesel Spill site. The site had diesel in soil that was independently investigated. Using that information, we determined the contamination was not a threat to human health or the environment.

Please direct questions and comments to the site manager:

Sara Fulton

509-319-0047 or sara.fulton@ecy.wa.gov

More information:

- Port of Moses Lake Diesel Spill website: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=14469.
- Eastern Regional Office, 4601 North Monroe Street, Spokane. (call 509-329-3415 for an appointment)

KITTITAS COUNTY

Pilot Travel Center 389

Facility Site ID# 18911356 Cleanup Site ID# 5649

1512 Hwy 97 Ellensburg

Groundwater Investigation Report Received

Date Report Received: 3/05/2018

Name of Report: Fourth Quarter 2017 Groundwater Monitoring Report

Date of Report: 1/31/2018

Type of Report: groundwater monitoring

Contaminants Reported: petroleum Affected Media: groundwater

Contact: Central Regional Office Public Records Coordinator

509-454-7658 or RecordsOfficer@ecy.wa.gov

KLICKITAT COUNTY

Pilot Travel Center 389

Facility Site ID# 18911356 Cleanup Site ID# 5649

1512 Hwy 97 Ellensburg

Work Plan Report Received

Date Report Received: 3/12/2018

Name of Report: Supplemental Remedial Investigation Work Plan

Date of Report: 3/5/2018

Type of Report: investigation work plan

Contaminants Reported: petroleum

Affected Media: soil, groundwater

Contact: Central Regional Office Public Records Coordinator

509-454-7658 or RecordsOfficer@ecy.wa.gov

OKANOGAN COUNTY

Omak Gull 611

Facility Site ID# 21391393 Cleanup Site ID# 5684

607 Okoma Dr Omak

Groundwater Monitoring Report Received

Date Report Received: 3/19/2018

Name of Report: Work Plan Supplemental Groundwater Monitoring

Date of Report: 3/13/2018
Type of Report: work plan
Contaminants Reported: petroleum
Affected Media: groundwater

Contact: Central Regional Office Public Records Coordinator

509-454-7658 or RecordsOfficer@ecy.wa.gov

SPOKANE COUNTY

Avista 601 E Riverside Site

Facility Site ID# 1822

Cleanup Site ID#

13181

601 East Riverside, Spokane

Determination of No Further Action

Ecology has determined that no further action is necessary at the Avista 601 E Riverside site. The site had metalscontaminated soil that was independently remediated. The site no longer poses a threat to human health or the environment.

Please direct questions and comments to the site manager:

Sara Fulton

509-319-0047 or sara.fulton@ecy.wa.gov

More information:

- Ecology's Avista 601 E Riverside webpage: https://fortress.wa.gov/ecv/gsp/Sitepage.aspx?csid=13181
- Eastern Regional Office, 4601 North Monroe Street, Spokane. (call 509-329-3415 for an appointment)

Brown Family Trust Site

Facility Site ID# 70243

Cleanup Site ID# 14466

706 1st Street, Cheney

Determination of No Further Action

Ecology has determined that no further action is necessary at the Brown Family Trust site. The site had polycyclic aromatic hydrocarbons (PAH) in soil that was independently cleaned up. The site is no longer a threat to human health or the environment.

Please direct questions and comments to the site manager:

Sara Fulton

509-319-0047 or sara.fulton@ecv.wa.gov

More information:

- Brown Family Trust website: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=14466
- Eastern Regional Office, 4601 North Monroe Street, Spokane. (call 509-329-3415 for an appointment)

City of Spokane CSO 34-1

Facility Site ID# 4752

Cleanup Site ID# 13308

2110 East Riverside Avenue, Spokane

Determination of No Further Action

Ecology has determined that no further action is necessary at the City of Spokane CSO 34-1 site. The site had polychlorinated biphenyl (PCB) contamination in soil that was independently investigated. Using that information, we determined the contamination is not a threat to human health or the environment.

Please direct questions and comments to the site manager:

Sara Fulton

509-319-0047 or sara.fulton@ecy.wa.gov

More information:

- Port of City of Spokane CSO 34-1 webpage: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=13308
- Eastern Regional Office, 4601 North Monroe Street, Spokane. (call 509-329-3415 for an appointment)

YAKIMA COUNTY

Yakima County Beverage

Facility Site ID# 38259534 Cleanup Site ID# 14

14490

1208 N 1st St, Yakima

Vapor Intrusion Report Received

Date Report Received: 2/28/2018

Name of Report: Historical Research and Vapor Intrusion Investigation

Date of Report: 9/27/2017
Type of Report: investigation
Contaminants Reported: petroleum
Affected Media: air (vapor)

Contact: Central Regional Office Public Records Coordinator

509-454-7658 or RecordsOfficer@ecy.wa.gov

Kwik Lok Yakima Pond Area

Facility Site ID# 20548

Cleanup Site ID#

13009

S 16th Ave & Lower Ahtanum Rd, Yakima

Determination of No Further Action

Ecology has determined that no further action is necessary at the Kwik Lok Yakima Pond Area site. The site had petroleum contamination in soil and groundwater.

More information may be found at: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=13009.

Contact: Jennifer Lind ator

509-454-7839 or jennifer.lind@ecy.wa.gov

Kwik Lok UST Area

Facility Site ID# 78125595 Cleanup Site ID#

12891

2712 S 16th Ave, Yakima

Determination of No Further Action

Ecology has determined that no further action is necessary at the Kwik Lok UST Area site. The site had petroleum contamination in soil and groundwater.

More information may be found at: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=12891.

Contact: Jennifer Lind ator

509-454-7839 or jennifer.lind@ecy.wa.gov

NEWS & NOTES

Cleanup Rule exploratory rulemaking scoping event happening Tuesday, April 3, 2018

The Washington State Department of Ecology (Ecology) is conducting an exploratory process to plan several future updates to the Cleanup Rule (Chapter 173-340 WAC). The rule contains regulations that implement our state's environmental cleanup law, the Model Toxics Control Act (MTCA, Chapter 70.105D RCW).

You're invited to participate in a webinar on Tuesday, April 3, 1:30pm–3:30pm. We want your suggestions for general rulemaking topics, and for specific changes to any part of the Cleanup Rule.

You can join us in person beginning at 1:00pm at our regional offices in Spokane, Union Gap, Lacey, or at the meeting hub at Embassy Suites in Bellevue. You can also join online beginning at 1:30pm via WebEx Chat, or call in just to listen. For details and log-in instructions, please see our **Exploratory Rulemaking Notice No. 2**.

Learn more about the exploratory rulemaking process. Find out more about the process and how you can participate by visiting our **Cleanup Rule website**. From there, you can enter comments on any part of the rule, or on the exploratory process itself. We're accepting comments through Sunday, April 15 using **eComment**, Ecology's online comment application. We'll catalog your comments and consider them at the most appropriate time during future rulemakings. You'll also have additional opportunities to comment on specific rule changes during future rulemakings.

For questions, please contact:

Clint Stanovsky, MS, MPA

Regulatory Analyst | Policy and Technical Support Unit

Toxics Cleanup Program, Washington Department of Ecology

 ${\bf clinton.stanovsky@ecy.wa.gov}$

360-407-7193 / Cell: 360-742-9703

P.O. Box 47600, Olympia, WA 98504-7600

300 Desmond Drive SE, Lacey, WA 98503-1274

GLOSSARY

Agreed order - A legal agreement with Ecology to make sure the cleanup meets the standards of Washington State's cleanup law, the Model Toxics Control Act (MTCA).

Cleanup action plan (CAP) - A document that describes the selected cleanup method(s) and specifies cleanup standards and other requirements. It is based on information and technical analyses generated during the RI/FS and consideration of public comments and community concerns. A draft of the CAP (DCAP) is made available for public review and comment before finalizing.

Comment period - A time period during which the public can review and comment on various documents and Ecology or EPA actions. For example, a comment period is provided to allow community members to review and comment on proposed cleanup action alternatives and proposed plans. Also, a comment period is held to allow community members to review and comment on draft feasibility studies.

Consent decree - A formal legal agreement that is filed with a court. It describes studies and/or cleanup work to be done at a site and the terms under which that work is to be done.

Engineering design report - Engineering design reports outline the specific details for implementation and operation of the first phase of the cleanup actions.

ERTS - Environmental Report Tracking System

Five-year periodic review - A periodic review is conducted at least every five years after the initiation of a cleanup action at a site, as required by the Model Toxics Control Act (MTCA). The purposes of the review are to evaluate site conditions, after cleanup is considered complete, and to ensure protection of human health and the environment

Formal cleanups - TCP conducts or supervises formal cleanups (also called formal oversight) when site owners are under court order or decree, or when cleanups are funded by legislative initiatives. Formal cleanups will meet MTCA standards. The public can provide input during public meetings and comment periods.

Hazardous Sites List - A statewide list of contaminated properties. Ecology may remove a site from the list only after determining that all remedial actions except confirmatory monitoring have been completed and compliance with the cleanup standards has been achieved at the site, or the listing was erroneous.

Independent cleanups - Property owners conduct independent cleanups on their own, or with help from our Voluntary Cleanup Program (VCP). Independent cleanups still meet MTCA standards, but property owners set their own timelines. Owners can ask for our help through the VCP but do not have to. They only need to hold public meetings or comment periods if a site needs to be de-listed.

Independent cleanup action - Any remedial action without department oversight or approval and not under an order or decree.

LUST - Leaking Underground Storage Tank

NFA - No Further Action

Public participation plan - Outlines and describes the tools Ecology will use to inform the public about site activities, and it identifies opportunities for the community to become involved in this process.

PSI - Puget Sound Initiative

RCW - Revised Code of Washington

Remedial action - Construction work done to clean up a contaminated site.

Remedial investigation/feasibility study - Two distinct but related studies. They are usually performed at the same time, and together referred to as the "RI/FS."

RI/FS - See Remedial Investigation/Feasibility Study

SEPA - State Environmental Policy Act

Site Hazard Assessment (SHA) - An assessment to gather information about a site to confirm whether a release of hazardous substances has occurred and to enable Ecology to evaluate the relative potential hazard posed by the release.

TCP - Ecology's Toxics Cleanup Program

Total petroleum hydrocarbons (TPH) - A term used to describe a large family of several hundred chemical compounds that originally come from crude oil. TPH is a mixture of chemicals made mainly from hydrogen and carbon.

UXO - Unexploded Ordnance

Voluntary Cleanup Program (VCP) - The VCP is one of several options for cleaning up a hazardous waste site under the state's cleanup law. Under this option, property owners may perform a cleanup independently and request services from Ecology for a fee.

WAC - Washington Administrative Code

WARM, Washington Ranking Method - The method used to rank sites placed on the Hazardous Sites List.

Find more glossary terms on Ecology's website: www.ecy.wa.gov/programs/tcp/tcp_acronym_list.htm

SITE INFORMATION ONLINE

Information on all Toxics Cleanup Program sites: https://fortress.wa.gov/ecy/gsp

Public Events related to the sites in this issue: https://fortress.wa.gov/ecy/publiccalendar/

REGIONAL OFFICES

Ecology Central Regional Office 1250 W. Alder St. Union Gap, WA 98903-0009

Ecology Northwest Regional Office 3190 160th Ave. SE Bellevue, WA 98008-5482

Ecology Eastern Regional Office 4601 N. Monroe Spokane, WA 99205-1295

Ecology Southwest Regional Office 300 Desmond Drive SE Lacey, WA 98503

Ecology Headquarters Office 300 Desmond Drive SE Lacey, WA 98503